

# PTX POWDER MEASURE STOP

[Reloading](#) > [Reloading Presses](#) > [Progressive Presses](#)

This component is an add-on to your Case Activated Powder Drop that allows the reloader to adjust the flare on cases utilizing the top and bottom adjustment screws. (Comes standard with new AP presses and CAPD)



## Attributes

- Name: [PTX POWDER MEASURE STOP](#)
- Manufacturer: [HORNADY](#)
- Product no.: 100031876
- Mfr. No.: 290049
- Delivery weight: 0.054kg
- Shipping height: 25mm
- Shipping width: 51mm
- Shipping length: 178mm
- UPC: 090255900491

## Item details

Made in USA

EU Export Disabled

# Table of Contents

- [Startpage](#)
- [PTX Powder Measure Stop Safety Instructions](#)
- [About Us](#)

# PTX Powder Measure Stop Safety Instructions

## Introduction

Thank you for choosing the PTX Powder Measure Stop. This component is designed to enhance your reloading experience by allowing adjustments to the flare on cases. It is important to follow these safety instructions to ensure safe use and compliance with the EU General Product Safety Regulation (GPSR).

## General Safety Guidelines

- Always read and understand the product manual before use.
- Ensure that the PTX Powder Measure Stop is compatible with your Case Activated Powder Drop.
- Keep this product out of reach of children and vulnerable individuals.
- Regularly inspect the product for any signs of wear or damage. Do not use if damaged.
- Follow all local laws and regulations regarding reloading and ammunition.

## Specific Safety Precautions for Use

- Use the PTX Powder Measure Stop only for its intended purpose as described in the product manual.
- Do not exceed the recommended adjustments for the flare on cases.
- Always wear appropriate safety gear, including safety glasses and gloves, when reloading.
- Ensure your workspace is clean and free from distractions while using the product.
- Store the PTX Powder Measure Stop in a dry, cool place when not in use.

## Instructions for Installation and Usage

### 1. Installation:

- Ensure your Case Activated Powder Drop is turned off and unplugged.
- Locate the top and bottom adjustment screws on your powder drop.
- Attach the PTX Powder Measure Stop according to the manufacturer's instructions provided in the product manual.
- Tighten the screws securely but do not overtighten to avoid damage.

### 2. Usage:

- Before making adjustments, ensure the powder drop is empty.
- Use the top and bottom adjustment screws to set the desired flare on your cases.
- Make small adjustments and test after each change to ensure proper functionality.
- Always doublecheck your settings before commencing reloading.

## Disposal Instructions

- Dispose of the PTX Powder Measure Stop in accordance with local regulations.
- Do not dispose of the product in household waste. Check for recycling options available in your area.
- If the product is damaged beyond repair, ensure it is disposed of safely to prevent accidents.

## Contact Information for Further Support

For any safety inquiries or further support regarding the PTX Powder Measure Stop, please refer to the manufacturer's contact information provided with your product.

By following these safety instructions, you can ensure a safe and effective reloading experience with your PTX Powder Measure Stop. Always prioritize safety and compliance with relevant regulations.

# About Us

## Brownells Deutschland

**Brownells Deutschland - Einer der größten Lieferanten für Waffenteile,  
Büchsenmacherwerkzeug & Schießsportzubehör**

Lahnstraße 1  
24539 Neumünster  
Deutschland

[www.brownells-deutschland.de](http://www.brownells-deutschland.de)