

## PTX POWDER MEASURE STOP

This component is an add-on to your Case Activated Powder Drop that allows the reloader to adjust the flare on cases utilizing the top and bottom adjustment screws. (Comes standard with new AP presses and CAPD)



### Attributes

- Name: PTX POWDER MEASURE STOP
- Manufacturer: HORNADY
- Product no.: 100031876
- Mfr. No.: 290049
- Delivery weight: 0.054kg
- Shipping height: 25mm
- Shipping width: 51mm
- Shipping length: 178mm
- UPC: 090255900491

### Item details

Made in USA  
EU Export Disabled

# Table of Contents

- Startpage
- Deutsch: HORNADY PTX Powder Measure Stop Sicherheitshinweise
- English: PTX Powder Measure Stop Safety Instructions

# HORNADY PTX Powder Measure Stop

## Sicherheitshinweise

### Einführung

Herzlichen Glückwunsch zu Ihrem Kauf des HORNADY PTX Powder Measure Stop! Dieses Produkt wurde entwickelt, um Ihnen beim Wiederladen von Munition zu helfen. Es ist wichtig, dass Sie die folgenden Sicherheitshinweise sorgfältig lesen und befolgen, um sicherzustellen, dass Sie das Produkt sicher und effektiv nutzen.

### Allgemeine Sicherheitsrichtlinien

- Das Produkt ist nur für den vorgesehenen Zweck zu verwenden.
- Halten Sie das Produkt außerhalb der Reichweite von Kindern.
- Verwenden Sie das Produkt nicht, wenn es beschädigt ist oder Anzeichen von Abnutzung zeigt.
- Achten Sie darauf, dass der Arbeitsbereich gut beleuchtet und frei von Ablenkungen ist.
- Tragen Sie bei der Verwendung geeignete Schutzausrüstung, wie z.B. Schutzbrille und Handschuhe.

### Spezifische Sicherheitsvorkehrungen für die Verwendung

- Stellen Sie sicher, dass alle Teile des HORNADY PTX Powder Measure Stop korrekt installiert sind, bevor Sie mit dem Laden beginnen.
- Vermeiden Sie den Kontakt mit der Haut und den Augen, insbesondere bei der Handhabung von Pulvern.
- Arbeiten Sie in einem gut belüfteten Bereich, um die Ansammlung von Dämpfen zu vermeiden.
- Verwenden Sie keine übermäßigen Kräfte beim Einstellen des Produkts, um Beschädigungen zu vermeiden.
- Überprüfen Sie regelmäßig die Einstellungen und die Funktionalität des Produkts, um sicherzustellen, dass es ordnungsgemäß funktioniert.

### Anweisungen zur Installation und Verwendung

#### 1. Installation

- Entfernen Sie das Produkt vorsichtig aus der Verpackung.
- Befestigen Sie den PTX Powder Measure Stop an Ihrem Case Activated Powder Drop gemäß den Anweisungen des Herstellers.
- Verwenden Sie die oberen und unteren Einstellschrauben, um die Ausbuchung an den Hülsen anzupassen.
- Stellen Sie sicher, dass alle Schrauben fest angezogen sind, bevor Sie mit dem Laden beginnen.

#### 2. Verwendung

- Füllen Sie den Powder Drop mit dem gewünschten Pulver.
- Stellen Sie die erforderliche Menge Pulver ein, indem Sie die Einstellschrauben entsprechend anpassen.
- Beginnen Sie mit dem Laden Ihrer Hülsen und überprüfen Sie regelmäßig die Pulvermenge.
- Beenden Sie den Ladevorgang und reinigen Sie das Produkt nach der Verwendung.

### Entsorgungsanweisungen

- Entsorgen Sie das Produkt gemäß den örtlichen Vorschriften für die Entsorgung von Haushaltsabfällen.
- Vermeiden Sie die Entsorgung in der Natur oder in Gewässern.
- Informieren Sie sich über spezielle Programme zur Rücknahme von gefährlichen Abfällen in Ihrer Nähe.

### Kontaktinformationen für weitere Unterstützung

Für Fragen oder weitere Informationen zu Ihrem HORNADY PTX Powder Measure Stop, wenden Sie sich bitte an den Hersteller oder Ihren Händler. Es ist wichtig, dass Sie bei Sicherheitsanfragen oder Problemen immer den richtigen Ansprechpartner konsultieren.

## **Schlussfolgerung**

Die Sicherheit bei der Verwendung des HORNADY PTX Powder Measure Stop liegt in Ihrer Verantwortung. Befolgen Sie diese Richtlinien sorgfältig, um ein sicheres und effektives Wiederladen zu gewährleisten. Bleiben Sie informiert und handeln Sie verantwortungsbewusst, um potenzielle Gefahren zu vermeiden.

# PTX Powder Measure Stop Safety Instructions

## Introduction

Thank you for choosing the PTX Powder Measure Stop. This component is designed to enhance your reloading experience by allowing adjustments to the flare on cases. It is important to follow these safety instructions to ensure safe use and compliance with the EU General Product Safety Regulation (GPSR).

## General Safety Guidelines

- Always read and understand the product manual before use.
- Ensure that the PTX Powder Measure Stop is compatible with your Case Activated Powder Drop.
- Keep this product out of reach of children and vulnerable individuals.
- Regularly inspect the product for any signs of wear or damage. Do not use if damaged.
- Follow all local laws and regulations regarding reloading and ammunition.

## Specific Safety Precautions for Use

- Use the PTX Powder Measure Stop only for its intended purpose as described in the product manual.
- Do not exceed the recommended adjustments for the flare on cases.
- Always wear appropriate safety gear, including safety glasses and gloves, when reloading.
- Ensure your workspace is clean and free from distractions while using the product.
- Store the PTX Powder Measure Stop in a dry, cool place when not in use.

## Instructions for Installation and Usage

### 1. Installation:

- Ensure your Case Activated Powder Drop is turned off and unplugged.
- Locate the top and bottom adjustment screws on your powder drop.
- Attach the PTX Powder Measure Stop according to the manufacturer's instructions provided in the product manual.
- Tighten the screws securely but do not overtighten to avoid damage.

### 2. Usage:

- Before making adjustments, ensure the powder drop is empty.
- Use the top and bottom adjustment screws to set the desired flare on your cases.
- Make small adjustments and test after each change to ensure proper functionality.
- Always doublecheck your settings before commencing reloading.

## Disposal Instructions

- Dispose of the PTX Powder Measure Stop in accordance with local regulations.
- Do not dispose of the product in household waste. Check for recycling options available in your area.
- If the product is damaged beyond repair, ensure it is disposed of safely to prevent accidents.

## Contact Information for Further Support

For any safety inquiries or further support regarding the PTX Powder Measure Stop, please refer to the manufacturer's contact information provided with your product.

By following these safety instructions, you can ensure a safe and effective reloading experience with your PTX Powder Measure Stop. Always prioritize safety and compliance with relevant regulations.