

Ultrapod Tripod with clamp - Black

Clamp any Kestrel device onto this sturdy and lightweight tripod to take measurements in the field. Portable and weather resistant, ideal for traveling and use in all weather conditions.

Technical data:

- Height (unfolded): 8 inches / 20 cm
- Length (folded): 7 inches / 18 cm
- Maximum load: 6 lbs (2.7 kg)
- Pan adjustment: 360 degrees
- Tilt adjustment: +/- 90 degrees
- Angle adjustment: +/- 20 degrees
- Dimensions (folded): 7" x 2" x 2" (17.8 cm x 5.1 cm x 5.1 cm)
- Weight: 4.2 oz (119 g)
- Material: Nylon (extremely break-resistant)
- Compatibility: Kestrel 1000-3500, Kestrel 4000 Series, Kestrel 5 Series.
The upper clamp can be removed and attached to any tripod with a standard tripod mount (1/4-20 thread).

The Portable Tripod with Clamp is the ideal accessory for anyone who wants to take precise Kestrel measurements in the field. The weather-resistant construction, adjustable legs and strong Velcro® strap make it versatile and stable, even in difficult conditions. Perfect for outdoor enthusiasts and professionals alike.

Attributes

- Name: Ultrapod Tripod with clamp - Black
- Manufacturer: KESTREL
- Product no.: BRD522013
- Mfr. No.: 0799
- Color: Black
- Delivery weight: 0.5kg
- Shipping height: 80mm
- Shipping width: 80mm
- Shipping length: 200mm
- UPC: 730650001170

Table of Contents

- [Startpage](#)
- [Deutsch: Sicherheitshinweise für das Ultrapod Tripod mit Klemme](#)
- [English: Ultrapod Tripod with Clamp Safety Instruction Guide](#)

Sicherheitshinweise für das Ultrapod Tripod mit Klemme

Einleitung

Vielen Dank, dass Sie sich für das Ultrapod Tripod mit Klemme entschieden haben. Dieses Produkt wurde entwickelt, um Ihnen bei der Durchführung präziser Messungen im Feld zu helfen. Um sicherzustellen, dass Sie das Produkt sicher und effektiv verwenden, haben wir diese Sicherheitshinweise zusammengestellt.

Allgemeine Sicherheitsrichtlinien

- Stellen Sie sicher, dass das Produkt für den vorgesehenen Zweck verwendet wird.
- Überprüfen Sie das Stativ regelmäßig auf Beschädigungen oder Abnutzung.
- Verwenden Sie das Stativ nicht in extremen Wetterbedingungen, die seine Stabilität beeinträchtigen könnten.
- Halten Sie das Produkt außerhalb der Reichweite von Kindern.
- Befolgen Sie alle Anweisungen und Warnhinweise in dieser Anleitung.

Spezifische Sicherheitsvorkehrungen für die Verwendung

- Verwenden Sie das Ultrapod Tripod nur mit kompatiblen KestrelGeräten (Kestrel 10003500, Kestrel 4000 Series, Kestrel 5 Series).
- Achten Sie darauf, dass die maximale Traglast von 6 lbs (2.7 kg) nicht überschritten wird.
- Stellen Sie sicher, dass die Klemme sicher am KestrelGerät befestigt ist, bevor Sie das Stativ verwenden.
- Vermeiden Sie es, das Stativ auf unebenen oder instabilen Oberflächen zu verwenden.
- Überprüfen Sie vor der Verwendung die Pan und Neigungseinstellungen, um sicherzustellen, dass sie korrekt eingestellt sind.

Anweisungen zur Installation und Verwendung

- **Installation:**
 1. Nehmen Sie die obere Klemme ab, falls erforderlich.
 2. Befestigen Sie die Klemme an Ihrem KestrelGerät.
 3. Setzen Sie die Klemme wieder auf das Stativ.
 4. Stellen Sie sicher, dass die Klemme fest sitzt und das Gerät sicher hält.
- **Verwendung:**
 1. Klappen Sie das Stativ auf, bis es die maximale Höhe von 8 Zoll (20 cm) erreicht.
 2. Stellen Sie das Stativ auf eine stabile Oberfläche.
 3. Justieren Sie die PanEinstellung auf 360 Grad und die Neigungseinstellung auf +/- 90 Grad, je nach Bedarf.
 4. Neigen Sie das Stativ bei Bedarf um +/- 20 Grad, um den besten Blickwinkel zu erhalten.
 5. Führen Sie Ihre Messungen durch, während das Stativ stabil steht.

Entsorgungsanweisungen

- Entsorgen Sie das Ultrapod Tripod gemäß den örtlichen Vorschriften für Elektro und ElektronikAltgeräte.
- Vermeiden Sie die Entsorgung im Hausmüll.
- Informieren Sie sich über Recyclingmöglichkeiten in Ihrer Nähe.

Kontaktinformationen für weitere Unterstützung

Für weitere Informationen oder bei Fragen zur Sicherheit Ihres Ultrapod Tripod mit Klemme wenden Sie sich bitte an den Hersteller oder den Vertriebspartner, bei dem Sie das Produkt erworben haben.

Bitte beachten Sie, dass Sie unsicheres Verhalten oder Produkte, die möglicherweise gefährlich sind, den zuständigen Behörden melden sollten. Überprüfen Sie regelmäßig die EU Safety GatePlattform auf Rückrufaktionen und Sicherheitsupdates.

Vielen Dank, dass Sie sich für Sicherheit und verantwortungsbewussten Umgang mit Ihrem Ultrapod Tripod entscheiden!

Ultrapod Tripod with Clamp Safety Instruction Guide

Introduction

Thank you for choosing the Ultrapod Tripod with Clamp. This tripod is designed to provide a stable platform for measuring with Kestrel devices in various outdoor conditions. To ensure safe and effective use, please follow the safety instructions and guidelines outlined in this document.

General Safety Guidelines

- **Product Safety:** This product is designed to be safe for use. However, it is essential to handle it with care to avoid accidents.
- **Enhanced Recalls:** Be aware that in the event of a safety issue, recall notices will be provided. You may receive remedies for any dangerous products.
- **Online Shopping:** If purchased online, ensure that the retailer complies with safety standards, similar to physical stores.
- **Special Consumer Focus:** Extra precautions should be taken when this product is used by or around children.
- **EU Contact Point:** For any safety inquiries, please refer to the designated EU contact point for assistance.
- **Rapid Alerts:** Stay informed about product safety updates through the EU's Safety Gate system.

Specific Safety Precautions for Use

- **Weight Limit:** Do not exceed the maximum load of 6 lbs (2.7 kg) to prevent tipping or breakage.
- **Stability:** Ensure that the tripod is set up on a stable surface to avoid accidents.
- **Weather Conditions:** While the tripod is weatherresistant, avoid using it in extreme weather conditions (e.g., heavy rain or strong winds) that may compromise stability.
- **Children:** Keep the tripod out of reach of children to prevent accidental injuries.
- **Inspection:** Regularly inspect the tripod for any signs of wear or damage before use. Do not use if damaged.

Instructions for Installation and Usage

1. Unfolding the Tripod:

- Carefully unfold the legs of the tripod until they are fully extended.
- Ensure that the legs are locked into place before use.

2. Attaching the Kestrel Device:

- Securely clamp your Kestrel device onto the tripod using the upper clamp.
- Ensure that the device is firmly attached to prevent it from falling.

3. Adjusting the Tripod:

- Use the pan adjustment to rotate the tripod head 360 degrees as needed.
- Adjust the tilt and angle using the tilt adjustment (+/- 90 degrees) and angle adjustment (+/- 20 degrees) for precise measurements.

4. Folding the Tripod:

- To fold the tripod, release the legs and carefully collapse them back into the folded position.
- Ensure that the tripod is stored in a dry place to maintain its condition.

Disposal Instructions

- Dispose of the Ultrapod Tripod responsibly.
- Follow local regulations for the disposal of plastic and nylon materials.
- If the tripod is damaged beyond repair, consider recycling the materials if possible.

Contact Information for Further Support

For any questions or concerns regarding the Ultrapod Tripod with Clamp, please refer to your retailer or the designated EU contact point for assistance.

Thank you for your attention to these safety instructions. Enjoy your Ultrapod Tripod and take accurate measurements safely!