

Sun visor - FDE - 50mm

[Optics & Mounting](#) > [Optic Accessories](#)

Brand: ZCO

Product: Sunshade

Size: 50mm

Color: FDE (Flat Dark Earth)



The ZCO Sunshade in 50mm size and FDE color is the perfect addition to your scope. It reduces glare and enhances visibility in bright light conditions. Crafted from durable material, it ensures reliable performance in all situations.

Attributes

- Name: [ZCO Zero Compromise Optics Sun visor - FDE - 50mm](#)
- Manufacturer: [ZCO Zero Compromise Optics](#)
- Product no.: BRD730012
- Mfr. No.: ZCO400677
- Color: Flat Dark Earth, FDE
- Size: 50mm
- Delivery weight: 1kg

Table of Contents

- [Startpage](#)
- [ZCO Zero Compromise Optics Sun Visor Safety Instructions](#)
- [About Us](#)

ZCO Zero Compromise Optics Sun Visor Safety Instructions

Introduction

Thank you for choosing the ZCO Zero Compromise Optics Sun Visor. This product is designed to enhance your shooting experience by reducing glare and improving visibility in bright light conditions. Please read this safety instruction guide carefully to ensure safe and effective use of the sun visor.

General Safety Guidelines

- Ensure that the sun visor is used only for its intended purpose.
- Regularly inspect the sun visor for any signs of damage or wear before each use.
- Keep the sun visor out of reach of children and vulnerable individuals.
- Follow all local laws and regulations regarding the use of optical accessories.
- In case of any safety concerns, please report them to the appropriate authorities.

Specific Safety Precautions for Use

- Always check the compatibility of the sun visor with your specific scope model.
- Avoid exposing the sun visor to extreme temperatures or harsh environmental conditions.
- Do not attempt to modify or disassemble the sun visor.
- Be cautious when handling the sun visor to avoid scratches or damage to the lens.
- If you notice any defects or malfunctions, discontinue use immediately and seek assistance.

Instructions for Installation and Usage

1. Installation:

- Ensure that your scope is clean and free from dust or debris.
- Align the sun visor with the front of the scope.
- Gently push the sun visor into place until it is securely attached.
- Verify that the sun visor is properly seated and does not obstruct your view.

2. Usage:

- When using the sun visor, position your scope in a way that maximizes visibility while minimizing glare.
- Adjust your shooting position as necessary to take full advantage of the sun visor's glare-reducing capabilities.
- If you experience any visibility issues while using the sun visor, remove it and assess the situation.

Disposal Instructions

- Dispose of the sun visor in accordance with local regulations regarding electronic waste and plastic materials.
- Do not dispose of the sun visor in regular household waste. Instead, take it to a designated recycling facility if available.

Contact Information for Further Support

For any inquiries regarding safety or product performance, please consult the product packaging or visit the

manufacturer's website for further assistance.

Thank you for your attention to these safety instructions. We hope you enjoy your ZCO Zero Compromise Optics Sun Visor.

About Us

Brownells Deutschland

**Brownells Deutschland - Einer der größten Lieferanten für Waffenteile,
Büchsenmacherwerkzeug & Schießsportzubehör**

Lahnstraße 1
24539 Neumünster
Deutschland

www.brownells-deutschland.de