

ZCO ZF 4-20X50 - FDE - MPCT1X - ccw - 10 MIL - NL

The ZCO ZC420s offer unrivalled optical performance and mechanical precision in an ultra-compact design.



With a length of 325 mm and a weight of only 986 g, they are ideal for applications that require maximum performance in a small size. The low magnification allows a wide field of view for close-up procedures, while the mechanical system offers a height adjustment of 35 mils.

Outstanding optical performance includes clarity, light transmission and resolution that set new standards.

The total light transmission is 92% and colour rendition is excellent.

The ZC420 are available in black and FDE.



The ZCO ZC420s offer unrivalled optical performance and mechanical precision in an ultra-compact design.

With a length of 325 mm and a weight of only 986 g, they are ideal for applications that require maximum performance in a small size. The low magnification allows a wide field of view for close-up procedures, while the mechanical system offers a height adjustment of 35 mils.

Outstanding optical performance includes clarity, light transmission and resolution that set new standards.

The total light transmission is 92% and colour rendition is excellent.

The ZC420 are available in black and FDE.



Attributes

- Name: ZCO ZF 4-20X50 - FDE - MPCT1X - ccw - 10 MIL - NL
- Manufacturer: ZCO Zero Compromise Optics
- Product no.: BRD730038
- Mfr. No.: ZCO4000582
- Color: FDE
- Magnification: 20x
- Min. Magnification: 4x
- Objective Size: 50mm
- Reticle: MPCT1X
- Delivery weight: 5kg

Table of Contents

- [Startpage](#)
- [Deutsch: Sicherheitshinweise für das ZCO ZF 420X50](#)
- [English: ZCO ZF 420X50 Safety Instruction Guide](#)

Sicherheitshinweise für das ZCO ZF 420X50

Einführung

Vielen Dank, dass Sie sich für das ZCO ZF 420X50 entschieden haben. Dieses Produkt bietet hervorragende optische Leistung und mechanische Präzision in einem kompakten Design. Um eine sichere Nutzung zu gewährleisten, beachten Sie bitte die folgenden Sicherheitshinweise und Anweisungen.

Allgemeine Sicherheitsrichtlinien

- Stellen Sie sicher, dass das Produkt vor der Verwendung auf sichtbare Schäden überprüft wird.
- Verwenden Sie das Produkt nur für den vorgesehenen Zweck.
- Halten Sie das Produkt außerhalb der Reichweite von Kindern.
- Achten Sie darauf, dass das Produkt nicht in die Hände von unbefugten Personen gelangt.
- Informieren Sie sich über Sicherheitswarnungen und Rückrufinformationen auf der EU Safety Gate Plattform.

Spezifische Sicherheitsvorkehrungen für die Nutzung

- Verwenden Sie das ZCO ZF 420X50 nicht bei extremen Wetterbedingungen (z. B. starker Regen oder Schnee).
- Vermeiden Sie es, das Produkt fallen zu lassen oder Stößen auszusetzen, da dies die optische Leistung beeinträchtigen könnte.
- Reinigen Sie die Linse mit einem weichen, trockenen Tuch, um Kratzer zu vermeiden.
- Verwenden Sie das Produkt nicht, wenn Sie unter dem Einfluss von Alkohol oder Drogen stehen.

Anweisungen für Installation und Nutzung

• Installation:

1. Montieren Sie das ZCO ZF 420X50 gemäß den Anweisungen des Herstellers.
2. Stellen Sie sicher, dass das Produkt fest und sicher angebracht ist, um ein Verrutschen zu verhindern.

• Nutzung:

1. Stellen Sie die Vergrößerung auf die gewünschte Stufe ein (4x bis 20x).
2. Nutzen Sie die Höheneinstellung von 35 Mils, um die Zielgenauigkeit zu optimieren.
3. Achten Sie darauf, dass Ihr Sichtfeld frei von Hindernissen ist, um die beste Leistung zu erzielen.

Entsorgungsanweisungen

- Entsorgen Sie das Produkt gemäß den örtlichen Vorschriften für elektronische Abfälle.
- Bringen Sie das Produkt zu einem autorisierten Recyclingzentrum, um umweltfreundliche Entsorgung sicherzustellen.

Kontaktinformationen für weitere Unterstützung

Für weitere Informationen und Unterstützung zu Ihrem Produkt, wenden Sie sich bitte an den Hersteller oder einen autorisierten Händler.

Bitte beachten Sie, dass die Sicherheit Ihrer Nutzung von größter Bedeutung ist. Bei Fragen oder Unsicherheiten zögern Sie nicht, Unterstützung zu suchen.

ZCO ZF 420X50 Safety Instruction Guide

Introduction

Thank you for choosing the ZCO ZF 420X50. This product is designed to provide exceptional optical performance and mechanical precision. To ensure safe and effective use, please follow the safety instructions outlined in this guide.

General Safety Guidelines

- Always read and understand the user manual before using the product.
- Ensure the product is used only for its intended purpose.
- Keep the product out of reach of children and vulnerable individuals.
- Regularly inspect the product for any signs of damage or wear.
- Always comply with local laws and regulations regarding the use of optical sights.
- Report any unsafe conditions or incidents to the appropriate authorities.

Specific Safety Precautions for Use

- Ensure that the ZCO ZF 420X50 is securely mounted to your firearm before use.
- Do not use the product if it appears damaged or malfunctioning.
- Avoid looking directly at the sun through the optical sight, as this can cause permanent eye damage.
- Use appropriate eye protection when using the product.
- Be mindful of your surroundings and ensure a clear line of sight when using the optical sight.
- Do not modify the product in any way as this may compromise safety and performance.

Instructions for Installation and Usage

Installation

1. Mounting the Optical Sight

- Choose a suitable mounting location on your firearm.
- Ensure that the mounting surface is clean and free from debris.
- Securely attach the ZCO ZF 420X50 using the provided mounting hardware.
- Confirm that the sight is level and properly aligned with the firearm.

2. Adjusting the Reticle

- Use the provided tools to adjust the reticle as needed for your specific shooting requirements.
- Refer to the product manual for detailed adjustment instructions.

Usage

1. Powering On/Off

- Follow the instructions in the manual for powering the optical sight on and off.

2. Adjusting Magnification

- Rotate the magnification dial to achieve the desired level of zoom, ranging from 4x to 20x.

3. Focusing the Sight

- Adjust the focus to ensure a clear image through the sight. This may involve adjusting the eyepiece or diopter.

4. Cleaning and Maintenance

- Regularly clean the lenses with a soft, lintfree cloth.
- Avoid using harsh chemicals or abrasive materials that could damage the lenses.

Disposal Instructions

- Dispose of the product in accordance with local regulations regarding electronic waste.
- Do not dispose of the product in household waste.
- Remove batteries and dispose of them separately if applicable.

Contact Information for Further Support

For any inquiries regarding safety or product performance, please refer to the manufacturer's website or contact their customer support service.

Thank you for your attention to these safety instructions. Enjoy using your ZCO ZF 420X50 with confidence!