

BORE CLEANING FOAM (AEROSOL) - GENERAL NANO PROTECTION

Reinigungsschaum Spray 100ml - 12 Dosen

[Gun Cleaning & Chemicals](#) > [Solvents & Degreasers](#) > [Bore Solvents](#)



Attributes

- Name: [GENERAL NANO PROTECTION Reinigungsschaum Spray 100ml - 12 Dosen](#)
- Manufacturer: [GENERAL NANO PROTECTION](#)
- Product no.: BRD811018
- Mfr. No.:
- Qty: 12
- Quantity: 1.2 l

Table of Contents

- [Startpage](#)
- [Safety Instruction Guide for GENERAL NANO PROTECTION BORE CLEANING FOAM \(AEROSOL\)](#)
- [About Us](#)

Safety Instruction Guide for GENERAL NANO PROTECTION BORE CLEANING FOAM (AEROSOL)

Introduction

Thank you for choosing GENERAL NANO PROTECTION BORE CLEANING FOAM (AEROSOL). This guide provides essential safety instructions to ensure the safe and effective use of this product. Please read the following information carefully before using the product.

General Safety Guidelines

- Always keep the product out of reach of children and pets.
- Ensure proper ventilation when using the product to avoid inhalation of fumes.
- Do not use the product near open flames or sources of ignition.
- Avoid contact with eyes and skin. If contact occurs, rinse immediately with plenty of water.
- Do not ingest the product. If swallowed, seek medical attention immediately.
- Store the product in a cool, dry place away from direct sunlight.
- Check the product for any damage before use. Do not use if the can is punctured or leaking.

Specific Safety Precautions for Use

- Use only in accordance with the instructions provided.
- Wear protective gloves and goggles when applying the foam to prevent skin and eye irritation.
- Do not spray the product on electrical equipment or live circuits.
- Avoid spraying in windy conditions to prevent overspray and unintended contact.
- Do not use the product for purposes other than those specified.

Instructions for Installation and Usage

1. Preparation:

- Shake the canister well before use.
- Ensure the area is wellventilated.

2. Application:

- Hold the can approximately 15-20 cm away from the bore.
- Press the nozzle to spray the foam directly into the bore.
- Allow the foam to sit for the recommended time as per the product label.

3. PostApplication:

- After the foam has settled, follow with a cleaning rod and brush to remove residue.
- Wipe any excess foam from surrounding areas with a clean cloth.

4. Cleaning Up:

- Dispose of any used materials according to local regulations.
- Ensure the canister is empty before disposal. Do not puncture or incinerate.

Disposal Instructions

- Dispose of the product and its container in accordance with local regulations.

- Do not dispose of the product in household waste.
- Check for local recycling programs that accept aerosol cans.

Contact Information for Further Support

For any safety inquiries or concerns regarding this product, please refer to the manufacturer's contact information provided on the product packaging.

By following these safety instructions, you can ensure a safe and effective experience with GENERAL NANO PROTECTION BORE CLEANING FOAM (AEROSOL). Thank you for your attention to these important guidelines.

About Us

Brownells Deutschland

**Brownells Deutschland - Einer der größten Lieferanten für Waffenteile,
Büchsenmacherwerkzeug & Schießsportzubehör**

Lahnstraße 1
24539 Neumünster
Deutschland

www.brownells-deutschland.de