

Accessories - Kestrel General - Ultrapod tripod with Clamp

[Shooting Accessories](#) > [Bipods, Monopods & Accessories](#) > [Bipods](#)

Clamp any Kestrel device onto this rugged and lightweight tripod to take measurements in the field. Portable and weather-resistant, it is ideal for travel and can be used in all weather conditions.

Technical Specifications:

Height (extended): 8 inches / 20 cm
Length (folded): 7 inches / 18 cm
Maximum load capacity: 6 lbs (2.7 kg)
Pan adjustment: 360 degrees
Tilt adjustment: ± 90 degrees
Angle adjustment: ± 20 degrees
Dimensions (folded): 7" x 2" x 2" (17.8 cm x 5.1 cm x 5.1 cm)
Weight: 4.2 oz (119 g)
Material: Nylon (extremely shatterproof)
Compatibility: Kestrel 1000-3500, Kestrel 4000 Series, Kestrel 5 Series. The top clamp can be removed and attached to any tripod with a standard tripod mount (1/4-20 thread).

NO IMAGE
AVAILABLE

Attributes

- Name: [Ultrapod tripod with Clamp](#)
- Manufacturer: [KESTREL](#)
- Product no.: EU2016437
- Mfr. No.: 0799
- Delivery weight: 1kg
- Shipping height: 100mm
- Shipping width: 100mm
- Shipping length: 100mm

Table of Contents

- Startpage
- Safety Instruction Guide for Kestrel General Ultrapod Tripod with Clamp
- About Us

Safety Instruction Guide for Kestrel General Ultrapod Tripod with Clamp

Introduction

Thank you for choosing the Kestrel General Ultrapod tripod with Clamp. This guide provides essential safety instructions to ensure the safe use of your tripod. Please read and follow these instructions carefully to avoid accidents and injuries.

General Safety Guidelines

- Always inspect the tripod before use for any signs of damage or wear.
- Ensure that the tripod is placed on a stable and level surface to prevent tipping.
- Do not exceed the maximum load capacity of 6 lbs (2.7 kg) to avoid structural failure.
- Keep the tripod away from extreme weather conditions that may affect its stability.
- Use the tripod only for its intended purpose, which is to support Kestrel devices.
- Store the tripod in a dry place when not in use to prevent damage from moisture.
- Be cautious when handling the tripod to avoid pinching fingers in moving parts.

Specific Safety Precautions for Use

- Ensure that the clamp is securely attached to the Kestrel device before taking measurements.
- Avoid sudden movements while using the tripod to maintain stability.
- Do not use the tripod in high winds or severe weather conditions that could cause it to topple.
- When adjusting the pan, tilt, or angle, make sure your hands are clear of moving parts.
- If using the tripod in a crowded area, be aware of your surroundings to prevent accidents.

Instructions for Installation and Usage

1. Setting Up the Tripod:

- Unfold the tripod legs and ensure they are fully extended.
- Adjust the height by pulling the leg sections to the desired height (maximum height: 8 inches / 20 cm).
- Ensure the legs are locked in place before use.

2. Attaching the Kestrel Device:

- Open the clamp by turning the adjustment knob counterclockwise.
- Place the Kestrel device into the clamp and secure it by turning the adjustment knob clockwise until it is tight.
- Ensure the device is stable and securely held by the clamp.

3. Adjusting the Tripod:

- To pan, gently rotate the device mounted on the clamp.
- For tilt adjustments, loosen the tilt adjustment knob, adjust the angle, and then tighten the knob.
- For angle adjustments, use the angle adjustment knob to set the desired angle within ± 20 degrees.

4. Packing the Tripod:

- To fold the tripod, reverse the setup steps by loosening the knobs and collapsing the legs.

- Store the tripod in a protective case if available, or keep it in a dry location.

Disposal Instructions

- Dispose of the tripod in accordance with local waste management regulations.
- If the tripod is damaged beyond repair, consider recycling the materials where possible, especially the nylon components.

Contact Information for Further Support

For any safety inquiries or support, please refer to the manufacturer's contact information provided with the product packaging. Always ensure you have the product details ready when seeking assistance.

By following these safety instructions, you can ensure a safe and effective use of your Kestrel General Ultrapod tripod with Clamp. Enjoy your measurements in the field!

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk