

# Accessories - Kestrel General - USB Data Transfer Cable for Kestrel 5000 series (IR)

[Gunsmith Tools](#) > [Measuring Tools](#)

This USB data cable enables a wired connection between all Kestrel 5 Series models and Windows/Mac computers with a USB port. It is ideal for installing firmware updates and transferring stored data via the Kestrel LiNK software.

Optical communication: Maintains the Kestrel's waterproof seal. No external power: No additional power supply required. Length: 3 feet (approx. 91 cm)  
Data rate: Up to 230 Kbps Lightweight: Only 2 oz (approx. 56 g), perfect for on-the-go use

NO IMAGE  
AVAILABLE

## Attributes

- Name: [USB Data Transfer Cable for Kestrel 5000 series \(IR\)](#)
- Manufacturer: [KESTREL](#)
- Product no.: EU2016453
- Mfr. No.: 0785
- Delivery weight: 1kg
- Shipping height: 100mm
- Shipping width: 100mm
- Shipping length: 100mm

# Table of Contents

- Startpage
- Kestrel General USB Data Transfer Cable Safety Instructions
- About Us

# Kestrel General USB Data Transfer Cable Safety Instructions

## Introduction

Thank you for choosing the Kestrel General USB Data Transfer Cable for Kestrel 5000 series (IR). This guide provides essential safety instructions and guidelines to ensure safe and effective use of the product. Please read this document carefully before using the cable.

## General Safety Guidelines

- Ensure the product is used only for its intended purpose, which is to facilitate a wired connection between Kestrel 5 Series models and Windows/Mac computers.
- Keep the cable away from extreme temperatures, moisture, and direct sunlight to prevent damage.
- Avoid using the cable in environments with high electromagnetic interference, which may disrupt data transmission.
- Regularly inspect the cable for signs of wear or damage. If any damage is found, discontinue use immediately.
- Store the cable in a safe place when not in use to prevent accidental damage or tripping hazards.

## Specific Safety Precautions for Use

- Do not expose the cable to water or other liquids. Although the Kestrel maintains a waterproof seal, the cable itself should remain dry.
- Do not attempt to disassemble or repair the cable. This may void any warranty and create safety hazards.
- Ensure that the cable is connected securely to both the Kestrel device and the computer before use.
- Do not use the cable if it is frayed, broken, or otherwise damaged.
- Keep the cable out of reach of children and pets to prevent accidents.

## Instructions for Installation and Usage

### 1. Connecting the Cable:

- Locate the USB port on your Kestrel 5 Series device.
- Connect one end of the USB data transfer cable to the Kestrel device and the other end to a USB port on your Windows or Mac computer.

### 2. Using Kestrel LiNK Software:

- Ensure you have the Kestrel LiNK software installed on your computer.
- Open the software after connecting the cable.
- Follow the onscreen instructions to install firmware updates or transfer stored data.

### 3. Data Transfer:

- Once connected, the software will automatically detect the Kestrel device.
- Select the desired data transfer option within the Kestrel LiNK software.
- Wait for the transfer process to complete before disconnecting the cable.

### 4. Disconnecting the Cable:

- After completing the data transfer, safely eject the Kestrel device from your computer.
- Disconnect the USB cable from both the Kestrel device and the computer.

- Store the cable properly to avoid damage.

## Disposal Instructions

- Dispose of the USB data transfer cable in accordance with local regulations regarding electronic waste.
- Do not dispose of the cable in regular household waste.
- If the cable is damaged beyond repair, consider recycling it at an appropriate facility.

## Contact Information for Further Support

For safety inquiries or additional support regarding the Kestrel General USB Data Transfer Cable, please refer to the manufacturer's contact information available on the product packaging or the official website.

## Conclusion

By following these safety instructions, you can ensure the safe and effective use of the Kestrel General USB Data Transfer Cable. Always stay informed about product recalls and safety updates through the EU's Safety Gate platform. Thank you for your attention to safety and for choosing Kestrel products.

# About Us

## Brownells UK

### **Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories**

Unit 1, Laughing Dog Industrial Estate  
London Road  
Rugby  
Warwickshire  
CV23 9LP

[www.brownells.co.uk](http://www.brownells.co.uk)