


GAS CHECKS - 7MM GAS CHECKS 1,000/BOX

[Reloading](#) > [Bullet Casting](#) > [Gas Checks](#)

If you cast your own bullets, Hornady's crimp-on gas checks will enhance their performance. During sizing, the gas check crimps to the base of cast lead bullets to seal gasses and protect the base from deformation. Hornady gas checks are the only real choice for bullet casters. Packaged 1000 per box.



Attributes

- Name: [7MM GAS CHECKS 1,000/BOX](#)
- Manufacturer: [HORNADY](#)
- Product no.: 749012044
- Mfr. No.: 7060
- Quantity: 1,000
- Delivery weight: 0.295kg
- Shipping height: 56mm
- Shipping width: 53mm
- Shipping length: 91mm
- UPC: 090255270600

Item details

Made in USA

US export classification: 0A505.x

Table of Contents

- Startpage
- Safety Instruction Guide for Hornady GAS CHECKS 7MM GAS CHECKS 1,000/BOX
- About Us

Safety Instruction Guide for Hornady GAS CHECKS 7MM GAS CHECKS 1,000/BOX

Introduction

Thank you for choosing Hornady GAS CHECKS 7MM. These crimp on gas checks are designed to enhance the performance of your cast lead bullets. This safety instruction guide provides essential information to ensure safe usage and compliance with the EU General Product Safety Regulation (GPSR).

General Safety Guidelines

- Ensure safe use of the product by following all instructions.
- Be aware of potential hazards associated with handling and using gas checks.
- Keep the product out of reach of children and vulnerable individuals.
- Report any unsafe products or accidents to the appropriate authorities.
- Check for recall updates on the EU's Safety Gate platform.

Specific Safety Precautions for Use

- Always wear appropriate personal protective equipment (PPE), such as gloves and safety glasses, when handling gas checks.
- Avoid inhaling any dust or particles generated during the sizing process.
- Do not use gas checks for any purpose other than intended use with cast lead bullets.
- Inspect gas checks for any damage before use. Do not use damaged gas checks.
- Store gas checks in a cool, dry place away from direct sunlight.

Instructions for Installation and Usage

1. Preparation:

- Ensure you have all necessary equipment, including your casting setup and sizing die.
- Clean the area where you will be working to avoid contamination.

2. Installation:

- Place the gas check on the base of the cast lead bullet.
- Use a sizing die to crimp the gas check securely to the bullet base.
- Ensure that the gas check is properly seated and crimped to prevent gas leakage.

3. Usage:

- Load the prepared bullets into your firearm according to the manufacturer's instructions.
- Always follow safe handling practices when loading and firing your firearm.

4. PostUsage:

- After use, clean any residue from your equipment and workspace.
- Dispose of any unused or damaged gas checks according to local regulations.

Disposal Instructions

- Dispose of gas checks and any related materials in accordance with local waste disposal regulations.
- Do not dispose of gas checks in general household waste if they are considered hazardous.

Contact Information for Further Support

For any inquiries regarding safety or product usage, please refer to the manufacturer's contact information provided on the packaging or the official website.

By following these guidelines, you can ensure safe and effective use of Hornady GAS CHECKS 7MM. Thank you for prioritizing safety in your reloading practices.

About Us

Brownells Česká republika

Brownells - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

www.brownells.cz