

ZC OPTIC ZF 8-40X56 - ZCO OPTIC ZF 8-40X56 - 36mm - TREMOR 5

ZC840

Our engineers have set a new standard for magnification, imaging performance and mechanical precision with the ZC840. This optical system offers outstanding performance and enables a perfect image even in the higher magnification range.



- Magnification: Over 30x for exceptional detail accuracy
- Top optical values: Outstanding contrast and resolution for a brilliant image
- Elevation adjustment range: 28 mils for precise settings over long distances
- Field of view: From 4.6m/100m to 1.0m/100m at 40x magnification for optimum target acquisition and tracking

With its impressive performance range, the ZC840 is the ideal choice for shooters who demand the best from their optics experience.

supporting your precision



ZC840 0.1MIL DATENBLATT



Abmaß	A	B	C	D	E	F	G	H	I	J	K
[mm]	175	70,5	53	62,5	80	63	36	28,7	27	45,75	48,5
[inch]	6.89	2.78	2.09	2.46	3.15	2.48	1.42	1.13	1.06	1.8	1.9

WWW.ZCOMPOPTI

2023 © Zero Compromise Optic GmbH
reserved. No guarantee for correct
accuracy of the information contained.

Attributes

- Name: ZCO OPTIC ZF 8-40X56 - 36mm - TREMOR 5
- Manufacturer: ZCO Zero Compromise Optics
- Product no.: BRD730004
- Mfr. No.: ZCO4000455
- Click Value: 0.1 MIL
- Color: Black
- Magnification: 40x
- Max Magnification: 40x
- Min. Magnification: 8x
- Objective Size: 56mm
- Reticle: TREMOR 5
- Scope Tube Diameter: 36mm
- Delivery weight: 5kg

Table of Contents

- Startpage
- Deutsch: Sicherheitshinweise für ZCO OPTIC ZF 840X56
- English: ZC OPTIC ZF 840X56 Safety Instruction Guide

Sicherheitshinweise für ZCO OPTIC ZF 840X56

Einführung

Herzlichen Glückwunsch zu Ihrem Kauf des ZCO OPTIC ZF 840X56. Dieses Produkt wurde entwickelt, um Ihnen eine präzise und zuverlässige Optik zu bieten. Um sicherzustellen, dass Sie das Beste aus Ihrem Produkt herausholen und gleichzeitig sicher bleiben, beachten Sie bitte die folgenden Sicherheitshinweise.

Allgemeine Sicherheitsrichtlinien

- Stellen Sie sicher, dass das Produkt nur für den vorgesehenen Zweck verwendet wird.
- Halten Sie das Produkt von Kindern fern, um Verletzungen oder Schäden zu vermeiden.
- Überprüfen Sie das Produkt regelmäßig auf Beschädigungen oder Abnutzung.
- Verwenden Sie das Produkt nicht, wenn es beschädigt ist oder Anzeichen von Fehlfunktionen zeigt.
- Beachten Sie alle örtlichen Gesetze und Vorschriften zur Verwendung von Optiken.

Spezifische Sicherheitsvorkehrungen für die Nutzung

- Verwenden Sie das ZCO OPTIC ZF 840X56 nur mit einem stabilen und sicheren Montagesystem.
- Stellen Sie sicher, dass das Zielfernrohr richtig kalibriert ist, bevor Sie es verwenden.
- Achten Sie darauf, dass Sie die richtige Vergrößerung wählen, um eine klare Sicht zu gewährleisten.
- Vermeiden Sie es, durch das Zielfernrohr zu schauen, wenn das Produkt nicht sicher montiert ist.
- Halten Sie das Zielfernrohr sauber und frei von Staub oder Schmutz, um die Sicht nicht zu beeinträchtigen.

Anweisungen zur Installation und Nutzung

1. Montage des Zielfernrohrs:

- Wählen Sie eine geeignete Montagebasis auf Ihrer Waffe.
- Befestigen Sie das Zielfernrohr sicher und stellen Sie sicher, dass es fest sitzt.
- Überprüfen Sie die Ausrichtung des Zielfernrohrs, um sicherzustellen, dass es korrekt justiert ist.

2. Einstellung der Vergrößerung:

- Drehen Sie den Vergrößerungsring, um die gewünschte Vergrößerung einzustellen (840x).
- Testen Sie die Vergrößerung auf ein entferntes Ziel, um sicherzustellen, dass es klar sichtbar ist.

3. Fokussierung:

- Verwenden Sie den Diopter zur Anpassung der Schärfe, um ein klares Bild zu erhalten.
- Stellen Sie sicher, dass der Diopter auf Ihre Sehstärke eingestellt ist.

4. Einstellung der Beleuchtung:

- Wählen Sie zwischen rotem oder grünem Licht, je nach Vorliebe und Lichtverhältnissen.
- Achten Sie darauf, dass die Beleuchtung nicht zu hell ist, um die Sicht nicht zu beeinträchtigen.

5. Sichtfeld und Augenabstand:

- Achten Sie darauf, dass Sie den richtigen Augenabstand (90 mm) einhalten, um eine optimale Sicht zu gewährleisten.
- Überprüfen Sie das Sichtfeld (4,6 m 1 m / 100 m), um sicherzustellen, dass Sie Ihr Ziel gut im Blick haben.

Entsorgungsanweisungen

- Entsorgen Sie das Produkt gemäß den örtlichen Vorschriften für Elektronik und Optikprodukte.
- Bringen Sie das Produkt zu einem autorisierten Recyclingzentrum oder einer Sammelstelle für Elektronikabfälle.
- Achten Sie darauf, alle Batterien oder elektronischen Komponenten umweltgerecht zu entsorgen.

Kontaktinformationen für weitere Unterstützung

Für weitere Informationen oder Unterstützung zu Ihrem Produkt, wenden Sie sich bitte an den Hersteller oder den Verkäufer, bei dem Sie das Produkt erworben haben. Sie sollten auch die Website des Herstellers besuchen, um aktuelle Informationen zu Sicherheitshinweisen und Rückrufen zu erhalten.

Bitte beachten Sie, dass diese Sicherheitshinweise im Einklang mit den EUVorgaben für Produktsicherheit stehen. Ihre Sicherheit ist uns wichtig, und wir empfehlen Ihnen, diese Hinweise sorgfältig zu befolgen, um ein sicheres und effektives Nutzungserlebnis zu gewährleisten.

ZC OPTIC ZF 840X56 Safety Instruction Guide

Introduction

Thank you for choosing the ZC OPTIC ZF 840X56. This guide provides essential safety instructions to ensure the safe and effective use of your optic. Please read this document carefully before using the product.

General Safety Guidelines

- Ensure that the product is used in accordance with the manufacturer's instructions.
- Always inspect the optic for any damage before use. Do not use if damaged.
- Keep the optic out of reach of children to prevent accidents.
- Use the product only for its intended purpose as outlined in this guide.
- Report any unsafe conditions or accidents to the relevant authorities.
- Regularly check for product recalls on the EU's Safety Gate platform.

Specific Safety Precautions for Use

- **Magnification Precautions:** Avoid looking directly at the sun through the optic, as this can cause severe eye damage.
- **Stability:** Ensure the optic is securely mounted to prevent it from falling or being dislodged during use.
- **Environmental Conditions:** Do not expose the optic to extreme temperatures, moisture, or direct sunlight for prolonged periods.
- **Cleaning:** Use only recommended cleaning materials to avoid scratching the lens. Do not use abrasive substances.
- **Transport:** When transporting the optic, use a protective case to prevent damage.

Instructions for Installation and Usage

1. Installation:

- Select a stable and secure mounting platform for the optic.
- Align the scope tube with the mounting rings and tighten securely.
- Ensure the optic is level and properly aligned with the firearm.

2. Usage:

- Adjust the magnification according to your shooting needs (8x to 40x).
- Use the elevation adjustment to zero in on your target. The adjustment range is 28 mils.
- Maintain a proper eye relief to ensure comfort and safety during use.
- Always ensure your target area is safe before using the optic.

Disposal Instructions

- Dispose of the optic in accordance with local regulations regarding electronic waste.
- Do not dispose of the product in regular household waste.
- Check for local recycling programs that accept optical equipment.

Contact Information for Further Support

For any safety inquiries or further assistance regarding the ZC OPTIC ZF 840X56, please refer to the manufacturer's website or customer support channels.

By following these guidelines, you can ensure a safe and enjoyable experience with your ZC OPTIC ZF 840X56. Thank you for your attention to these important safety instructions.