

Weather & Environmental Meters - Kestrel 5500 Weather Meter with LiNK + Vane Mount

[Shooting Accessories](#) > [Windmeters & Flags](#) > [Windmeters](#)

Experience the future of weather measurement with the Kestrel 5500 Weather Meter. This high-precision instrument delivers comprehensive environmental data and is ideal for outdoor activities such as golfing, sailing, aviation, shooting, and spraying applications.

Key Functions:

- Precision Measurements: Accurately measures all critical environmental conditions, including wind direction, crosswind, headwind, and tailwind
- Rugged and Durable: Drop-tested, dustproof, waterproof, and built to withstand extreme environments
- Advanced Display: Large, high-resolution screen with dual-color backlighting and a durable polycarbonate lens
- Data Logging: Stores over 10,000 time-stamped data points; data transfer via the LiNK app or USB cable (sold separately)

NO IMAGE
AVAILABLE

Smartphone Connectivity:

With optional LiNK iOS/Android connectivity, data can be transmitted wirelessly in real time to your mobile device.

Compact and Versatile:

When paired with the Kestrel Vane Mount, the unit mounts to a tripod and becomes a full-featured weather station—ideal for continuous wind speed and wind direction monitoring.

Rely on the Kestrel 5500—a weather meter proven to perform reliably even in the harshest conditions. Perfect for professionals and outdoor enthusiasts worldwide.

Attributes

- Name: [Kestrel 5500 Weather Meter with LiNK + Vane Mount](#)
- Manufacturer: [KESTREL](#)
- Product no.: EU2016377
- Mfr. No.: 0855LVYEL
- Delivery weight: 1kg
- Shipping height: 100mm
- Shipping width: 100mm
- Shipping length: 100mm

Table of Contents

- Startpage
- Safety Instructions for Kestrel 5500 Weather Meter
- About Us

Safety Instructions for Kestrel 5500 Weather Meter

Introduction

Thank you for choosing the Kestrel 5500 Weather Meter with LiNK + Vane Mount. This highprecision instrument is designed to provide you with accurate environmental data for various outdoor activities. To ensure safe and effective use of this product, please read and follow these safety instructions carefully.

General Safety Guidelines

- **Product Safety:** The Kestrel 5500 has been designed and tested to ensure safe use. Please ensure that you follow all instructions for safe operation.
- **Enhanced Recalls:** Stay informed about any product recalls. If you receive a recall notice, follow the instructions provided to ensure your safety.
- **Online Shopping:** If you purchased this product online, ensure that the vendor complies with safety standards equivalent to those of physical stores.
- **Special Consumer Focus:** This product is not intended for use by children. Keep it out of reach of children to prevent accidents.
- **EU Contact Point:** For any safety inquiries, please contact the manufacturer or the retailer from whom you purchased this product.
- **Rapid Alerts:** Stay updated on product safety by checking the EU's Safety Gate platform for any alerts regarding unsafe products.

Specific Safety Precautions for Use

- **Avoid Extreme Conditions:** Do not expose the Kestrel 5500 to extreme temperatures or conditions outside its specified operating range.
- **Handle with Care:** Although the device is rugged and durable, avoid dropping it or subjecting it to unnecessary impact.
- **Water Resistance:** While the Kestrel 5500 is waterproof, ensure that all ports and covers are securely closed before exposure to water.
- **Battery Safety:** Use only the recommended battery type. Do not attempt to recharge nonrechargeable batteries.
- **Data Logging:** When using the data logging feature, ensure that the device is securely mounted to avoid accidental drops.
- **Smartphone Connectivity:** When using the LiNK app, ensure that your mobile device is compatible and properly configured to avoid connectivity issues.

Instructions for Installation and Usage

- **Installation:**

1. **Mounting:** If using the Kestrel Vane Mount, securely attach the Kestrel 5500 to the mount and ensure it is firmly fixed to a tripod.
2. **Power On:** Press the power button to turn on the device. Allow it to calibrate before taking measurements.

- **Usage:**

1. **Selecting Functions:** Use the buttons to navigate through the various measurement options (e.g., wind speed, temperature).
2. **Data Logging:** To log data, select the data logging feature from the menu. Ensure the device is

stable during measurement.

3. **Transferring Data:** Connect the device to your mobile device using the LiNK app or USB cable to transfer logged data.
4. **Regular Maintenance:** Clean the device with a soft, dry cloth. Do not use solvents or abrasive materials.

Disposal Instructions

- **Battery Disposal:** Dispose of used batteries in accordance with local regulations. Do not throw batteries in the regular trash.
- **Device Disposal:** When the Kestrel 5500 reaches the end of its life, dispose of it in accordance with local electronic waste disposal regulations.
- **Environmental Considerations:** Ensure that all components are disposed of responsibly to minimize environmental impact.

Contact Information for Further Support

For any questions or concerns regarding the Kestrel 5500 Weather Meter, please refer to the manufacturer's website or the retailer from whom you purchased the product for support and assistance.

Thank you for your attention to these safety instructions. Enjoy using your Kestrel 5500 Weather Meter responsibly!

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk