

Weather & Environmental Meters - Kestrel 5500 Weather Meter with LiNK + Vane Mount

[Shooting Accessories](#) > [Windmeters & Flags](#) > [Windmeters](#)

Experience the future of weather measurement with the Kestrel 5500 Weather Meter. This high-precision instrument delivers comprehensive environmental data and is ideal for outdoor activities such as golfing, sailing, aviation, shooting, and spraying applications.

Key Functions:

- Precision Measurements: Accurately measures all critical environmental conditions, including wind direction, crosswind, headwind, and tailwind
- Rugged and Durable: Drop-tested, dustproof, waterproof, and built to withstand extreme environments
- Advanced Display: Large, high-resolution screen with dual-color backlighting and a durable polycarbonate lens
- Data Logging: Stores over 10,000 time-stamped data points; data transfer via the LiNK app or USB cable (sold separately)

NO IMAGE
AVAILABLE

Smartphone Connectivity:

With optional LiNK iOS/Android connectivity, data can be transmitted wirelessly in real time to your mobile device.

Compact and Versatile:

When paired with the Kestrel Vane Mount, the unit mounts to a tripod and becomes a full-featured weather station—ideal for continuous wind speed and wind direction monitoring.

Rely on the Kestrel 5500—a weather meter proven to perform reliably even in the harshest conditions. Perfect for professionals and outdoor enthusiasts worldwide.

Attributes

- Name: [Kestrel 5500 Weather Meter with LiNK + Vane Mount](#)
- Manufacturer: [KESTREL](#)
- Product no.: EU2016378
- Mfr. No.: 0855L VOLV
- Delivery weight: 0.3kg
- Shipping height: 45mm
- Shipping width: 28mm
- Shipping length: 127mm

Table of Contents

- Startpage
- Safety Instruction Guide for Kestrel 5500 Weather Meter
- About Us

Safety Instruction Guide for Kestrel 5500 Weather Meter

Introduction

Thank you for choosing the Kestrel 5500 Weather Meter with LiNK + Vane Mount. This highprecision instrument is designed to provide accurate environmental data for various outdoor activities. To ensure safe and effective use of this product, please read and follow the safety instructions outlined in this guide.

General Safety Guidelines

- **Product Safety:** This product is designed to meet safety standards for nonfood items. Ensure proper use to avoid risks.
- **Enhanced Recalls:** Stay informed about product recalls and safety notices. If you receive a recall notice, follow the instructions provided.
- **Online Shopping:** If purchased online, ensure the seller complies with safety regulations.
- **Special Consumer Focus:** Extra care should be taken when using this product around children or vulnerable individuals.
- **EU Contact Point:** For safety inquiries, refer to the designated EU contact point for this product.
- **Rapid Alerts:** Monitor the EU Safety Gate platform for updates on unsafe products.

Specific Safety Precautions for Use

- **Avoid Extreme Conditions:** Do not expose the Kestrel 5500 to extreme temperatures beyond the specified operating range.
- **Handle with Care:** Although the device is rugged, avoid dropping or subjecting it to strong impacts.
- **Water Resistance:** Ensure that the device's water resistance features are intact before using it in wet conditions.
- **Battery Safety:** Use only the recommended battery type and replace it according to the manufacturer's instructions.
- **Data Privacy:** Be aware of data privacy when using the LiNK app for connectivity. Ensure your device is secure.

Instructions for Installation and Usage

1. **Unboxing:** Carefully remove the Kestrel 5500 from its packaging. Check for all included components.
2. **Battery Installation:**
 - Open the battery compartment.
 - Insert the recommended batteries, ensuring correct polarity.
 - Close the compartment securely.
3. **Connecting the Vane Mount:**
 - Attach the Kestrel 5500 to the Kestrel Vane Mount.
 - Secure it to a tripod if needed for stability.
4. **Powering On:** Press the power button to turn on the device. The display will illuminate.
5. **Calibrating the Device:** Follow onscreen instructions for calibration to ensure accurate measurements.
6. **Using the LiNK App:**
 - Download the LiNK app from your device's app store.
 - Follow the app's instructions to connect your Kestrel 5500 for realtime data transmission.
7. **Taking Measurements:**
 - Hold the device in a stable position to obtain accurate readings.
 - Use the directional vane for wind measurements.
8. **Data Logging:** Review stored data points through the device or via the LiNK app.

Disposal Instructions

- **Battery Disposal:** Dispose of used batteries in accordance with local regulations for hazardous waste.
- **Device Disposal:** When the Kestrel 5500 reaches the end of its life, recycle it in accordance with local electronic waste disposal regulations.
- **Packaging Disposal:** Recycle packaging materials where facilities exist.

Contact Information for Further Support

For any questions or concerns regarding the Kestrel 5500 Weather Meter, please refer to the manufacturer's contact information provided with your product.

Thank you for using the Kestrel 5500 Weather Meter responsibly. Your safety is our priority.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk