

Powder Measure Knob with Absolute Position (Small Powder Bar (pistol))

[Reloading](#) > [Reloading Presses](#) > [Reloading Press Accessories](#)

Elevate your reloading precision with our premium Powder Measure Knob, featuring an integrated, tactile click-mechanism and a rotating scale. Designed for ultimate accuracy, it offers 50 precise dial divisions for micro-adjustments, covering up to 15 full rotations of the powder bar's throw range. Inside, a custom-machined, spring-tensioned bolt completely eliminates thread backlash, ensuring exceptionally smooth, stable, and repeatable adjustments every time.



Specifications

Adjustment Increments: 50 tactile dial divisions

Adjustment Range: Up to 15 full rotations

Backlash Elimination: Custom-machined, spring-tensioned bolt

Installation: Quick setup; includes dedicated mounting screw and washer

Attributes

- Name: [Powder Measure Knob with Absolute Position \(Small Powder Bar \(pistol\)\)](#)
- Manufacturer: [ARMANOV](#)
- Product no.: EU2018214
- Mfr. No.: APKNB-P
- Colour: Black
- Delivery weight: 1kg
- Shipping height: 100mm
- Shipping width: 100mm
- Shipping length: 100mm

Table of Contents

- [Startpage](#)
- [Safety Instruction Guide for Powder Measure Knob with Absolute Position](#)
- [About Us](#)

Safety Instruction Guide for Powder Measure Knob with Absolute Position

Introduction

Thank you for choosing the Powder Measure Knob with Absolute Position. This product is designed to enhance your reloading precision and ensure safe operation. Please read this safety instruction guide carefully to understand how to use the product safely and effectively.

General Safety Guidelines

- Ensure that the product is used in accordance with the instructions provided to avoid any potential hazards.
- Always keep the product out of reach of children and vulnerable individuals.
- Regularly inspect the product for any signs of wear or damage before use.
- Do not use the product if it appears to be damaged or malfunctioning.
- Follow all local laws and regulations regarding the use of reloading equipment.

Specific Safety Precautions for Use

- Always wear appropriate safety gear, including safety glasses, when using the Powder Measure Knob.
- Avoid placing your fingers near the moving parts of the powder measure during operation.
- Ensure that the powder measure is securely mounted before making any adjustments.
- Do not exceed the recommended adjustments specified in the product specifications.
- Be cautious when handling powders and ensure proper ventilation in your work area.

Instructions for Installation and Usage

Installation

1. **Preparation:** Gather all necessary tools, including the dedicated mounting screw and washer provided with the product.
2. **Mounting:**
 - Select a stable surface for mounting the Powder Measure Knob.
 - Use the provided mounting screw and washer to secure the knob in place.
 - Ensure that the knob is firmly attached and does not wobble.
3. **Adjustment Setup:**
 - Familiarize yourself with the tactile click mechanism and rotating scale before making adjustments.

Usage

1. **Adjusting the Powder Measure:**
 - Rotate the knob to the desired position, ensuring you utilize the 50 precise dial divisions for microadjustments.
 - Make sure to stay within the 15 full rotations of the powder bar's throw range.
2. **Monitoring:**
 - Regularly check the settings after each use to ensure accuracy.
 - If you notice any backlash or instability, refer to the troubleshooting section or contact support.
3. **PostUse Care:**
 - Clean the product after each use to maintain its performance.
 - Store the product in a dry and safe location, away from children.

Disposal Instructions

- Dispose of the product in accordance with local regulations for electronic and mechanical waste.
- Do not throw the product in regular household waste.
- Consider recycling where possible to minimize environmental impact.

Contact Information for Further Support

For any inquiries or concerns regarding the safety of this product, please reach out to the designated EU contact point. Ensure that all safety guidelines are followed to maintain a safe reloading environment.

Thank you for prioritizing safety while using the Powder Measure Knob with Absolute Position. Your attention to these guidelines ensures a safer experience for everyone involved in the reloading process.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk