

Powder Measure Knob with Absolute Position (Large Powder Bar)

Elevate your reloading precision with our premium Powder Measure Knob, featuring an integrated, tactile click-mechanism and a rotating scale. Designed for ultimate accuracy, it offers 50 precise dial divisions for micro-adjustments, covering up to 15 full rotations of the powder bar's throw range. Inside, a custom-machined, spring-tensioned bolt completely eliminates thread backlash, ensuring exceptionally smooth, stable, and repeatable adjustments every time.



Specifications

Adjustment Increments: 50 tactile dial divisions

Adjustment Range: Up to 15 full rotations

Backlash Elimination: Custom-machined, spring-tensioned bolt

Installation: Quick setup; includes dedicated mounting screw and washer

Attributes

- Name: Powder Measure Knob with Absolute Position (Large Powder Bar)
- Manufacturer: ARMANOV
- Product no.: EU2018215
- Mfr. No.: APKNB-R
- Colour: Black
- Delivery weight: 1kg
- Shipping height: 100mm
- Shipping width: 100mm
- Shipping length: 100mm

Table of Contents

- [Startpage](#)
- [English: Safety Instruction Guide for Powder Measure Knob with Absolute Position](#)

Safety Instruction Guide for Powder Measure Knob with Absolute Position

Introduction

Thank you for choosing the Powder Measure Knob with Absolute Position (Large Powder Bar). This product is designed to enhance your reloading experience by providing precision and ease of use. It is essential to follow safety guidelines to ensure safe operation and to maximize the effectiveness of this product.

General Safety Guidelines

- Always read and understand the product instructions before use.
- Ensure that the workspace is clean and free of obstructions.
- Keep the product out of reach of children and vulnerable individuals.
- Regularly inspect the product for any signs of wear or damage.
- Report any unsafe conditions or incidents to the appropriate authorities.
- Check for recall updates on the EU's Safety Gate platform.

Specific Safety Precautions for Use

- Do not exceed the specified adjustment range of up to 15 full rotations.
- Ensure that all adjustments are made while the product is at rest to avoid accidental movements.
- Avoid using excessive force when adjusting the knob to prevent damage.
- Do not use the product if it appears to be damaged or malfunctioning.
- Always follow the recommended loading procedures to prevent accidents.

Instructions for Installation and Usage

Installation

1. **Unpack the Product:** Carefully remove the Powder Measure Knob from the packaging.
2. **Check Components:** Ensure that the dedicated mounting screw and washer are included.
3. **Mounting the Knob:**
 - Align the knob with the mounting hole on the powder measure.
 - Insert the mounting screw through the knob and into the powder measure.
 - Tighten the screw securely, but do not overtighten to avoid damaging the threads.
4. **Final Inspection:** Ensure that the knob is securely attached and functions smoothly.

Usage

1. **Adjusting the Knob:**
 - Rotate the knob to make adjustments. Use the tactile divisions to achieve the desired setting.
 - For microadjustments, count the divisions to ensure precision.
2. **Loading Powder:**
 - Follow the manufacturer's recommended procedures for loading powder.
 - Ensure the powder measure is stable before making any adjustments.
3. **After Use:**
 - Clean the knob and surrounding area to prevent powder residue buildup.
 - Store the product in a safe location away from children.

Disposal Instructions

- Dispose of the product in accordance with local regulations.

- Do not dispose of the product in household waste.
- Consider recycling options if available.

Contact Information for Further Support

For any questions or concerns regarding the Powder Measure Knob with Absolute Position, please refer to the manufacturer's website or contact their customer support for assistance.